



NuGen I.T.

Responses to CCIF Parts and Materials Committee

- ❑ **Does your system allow you to grade parts?**
 - ❑ **YES. Enterprise *Workflow* allows the customer to grade parts.**
- ❑ **If so, how?**
 - ❑ **Parts are graded through an interactive, documented means by the parts supplier**
 - ❑ **Grading is based on industry-accepted ARA standards**

❑ What tools does your system provide to help recyclers meet industry standards, i.e. ARA Damage Codes, Parts Inclusions, etc.?

❑ Enterprise *Workflow* includes the standards established by the ARA for

- ❑ Damage location
- ❑ Type of damage
- ❑ Severity
- ❑ Condition

Parts Report/Request - Microsoft Internet Explorer

Company: Southwest Insurance Co - Todd Johnson
 Claim Number: 20040604 01
 Estimating Platform: Mitchell

Submit your response using the following link:
<http://www.viewclaim.com/PartResponse/ER.asp?key=B22JEG>

Year: 02	Style: 2D Conv
Make: Mazda	Engine:
Model: Miata	VIN: JM1NB353020223131

Images: (available only when viewing on-line in a separate browser window, double-click to enlarge)

Part Number	Description	Qty
NOY1-50-030A	FRT BUMPER COVER	1
NA01-50-101A	FRT BUMPER COVER GRILLE	1
NCY0-52-61XG	LUGGAGE LID PANEL	1
NCY0-52-110F	R FENDER PANEL	1
NC72-51-0K0D	R FRT COMBINATION LAMP ASSEMBLY	1
NCY2-58-02XD	R FRT DOOR SHELL	1
NCY0-70-400A	R QUARTER OUTER PANEL	1

Response to Part Request

FROM:

Company: Halifax Recyclers Remember Me (next visit)
 Contact: Tom Barnett
 Telephone: 902-423-6331
 e-Mail Address: tbarnet@hrecyclers.ca

FOR VEHICLE: Year: 02 Make: Mazda Model: Miata VIN: JM1NB353020223131

Part Number	Description	Qty	Qty	Amount(each)	Notes / Damage Codes
NOY1-50-030A	FRT BUMPER COVER	1			
NA01-50-101A	FRT BUMPER COVER GRILLE	1			
NCY0-52-61XG	LUGGAGE LID PANEL	1			
NCY0-52-110F	R FENDER PANEL	1	1	75	SH2
NC72-51-0K0D	R FRT COMBINATION LAMP ASSEMBLY	1	1	200	No Damage
NCY2-58-02XD	R FRT DOOR SHELL	1	1	350	SD1, RED
NCY0-70-400A	R QUARTER OUTER PANEL	1			

ARA Damage Locator

ARA Damage Locator

Bumpers and End Panels only use #1 and #6 when they wrap around the side

Damage Locations always follow the same pattern: Front to back, top to bottom, left to right as seen from driver's seat in an "S" pattern, with locations for door handles and mirrors. Codes are location, damage, and hours. Example "2D1" is a one hour dent in location 2. There may be a primary and secondary code per part, as in "2DASZ". If there is no damage on a part the code is 000 (as in three zeros). Zero as a location indicates the entire panel, as in 004 (all over hood damage, 4 Hrs).

Damage Code Table

B = Burn	C = Crease	R = Rust on Surface
D = Dent	E = Bent	P = Parking Lot Dings
L = Lip	K = Buckle	S = Scratch - Surface Only
H = Hair	J = Rip or crack	T = Paint Problem
000 = No Damage (all zero)		

- ❑ **How does your system assist all stakeholders in locating recycled parts and/or gain access to recycled parts data?**
 - ❑ **Enterprise *Workflow* is designed as an enabler to all trading partners**
 - ❑ **Offers an easy-to-use, open Internet interface**
 - ❑ **Incorporates detailed parts usage analysis**

- ❑ **Who are your parts partners?**
 - ❑ **Collision repairers and insurers utilize the recycling trading partners of their choice**
 - ❑ **Enterprise *Workflow* does not bias the user toward any parts supplier**

- ❑ **How do all stakeholders gain access to recycled parts and recycled parts data?**
 - ❑ **Parts are accessed via a common, open interface based on Internet technology**
 - ❑ **Recycled parts data can be accessed via an interactive MIS reporting tool**

Requested			Response		
Part Number	Description	Qty	Qty	Amount(each)	Part Notes
N0Y1-50-030A	FRT BUMPER COVER	1			
NA01-50-101A	FRT BUMPER COVER GRILLE	1			
NCY0-52-61XG	LUGGAGE LD PANEL	1			
NCY0-52-110F	R FENDER PANEL	1	1	75	OH2
NCT2-51-0K0D	R FRT COMBINATION LAMP ASSEMBLY	1	1	200	No Damage
NCY2-58-02XD	R FRT DOOR SHELL	1	1	350	SD1, RED
NCY0-70-400A	R QUARTER OUTER PANEL	1			

Claim	Status	Platform	Total	RO	Part %	New Qty	New \$ /	AM Qty	AM \$	LKQ Qty	LKQ \$
JAF20045271124	In Work	ADP	\$1,051.72		66.41 %	99.90 %	83.44 %	0.00 %	0.00 %	0.00 %	0.00 %
JAF20045271126	In Work	ADP	\$180.37		93.88 %	99.90 %	100.00 %	0.00 %	0.00 %	0.00 %	0.00 %
7 Assignment(s)			\$7,113.18		41.13 %	57.10 %	41.54 %	0.00 %	0.00 %	0.00 %	0.00 %
Estimator: Heska, Mike											
REM20045271443	Completed	ADP	\$715.99		15.67 %	0.00 %	0.00 %	0.00 %	0.00 %	0.00 %	0.00 %
SOA20045271414	Completed	ADP	\$3,609.81		32.92 %	83.32 %	32.36 %	16.66 %	17.42 %	0.00 %	0.00 %
2 Assignment(s)			\$4,325.80		24.29 %	41.66 %	16.18 %	8.33 %	8.71 %	0.00 %	0.00 %
9 Assignment(s)			\$11,438.98		37.39 %	53.67 %	35.91 %	1.85 %	1.94 %	0.00 %	0.00 %
327 Assignment(s)			\$769,207.44	31	45.57 %	64.22 %	52.91 %	6.92 %	4.66 %	5.65 %	6.80 %

- ❑ **How does your system promote recycled parts to the key stakeholders?**
 - ❑ **Ease of access through pre-stored supplier information by the user**
 - ❑ **Common, open interface that does not require any proprietary software (internet browser)**
 - ❑ **An interactive rules processor ensures compliance and promotes recycled parts usage based upon agreed policies and procedures**

The screenshot shows a 'Rule Wizard' window with the following configuration:

- Data Element to Test:** [Dropdown menu]
- Test Value:** [Dropdown menu]
- Buttons:** + Data Element, + Test Expression, + 'AND', + 'OR'
- IF... Expression:** [Vehicle AGE] >= 3 AND [Part Amount LKQ] = 0 AND [Part Amount ReMfg] = 0
- ACTION:**
 - Approve
 - Disapprove
 - Manual Review [n/a]
 - Go to ruleset [n/a]
 - Continue with next rule
 - Flag For Reinspection
 - Flag For Audit
 - Set Score = 0
 - Increment Score []
- Log Message:** Vehicle is at least 3 years old. You must check for Recycled or LKQ parts.
- Buttons:** OK, Cancel, Check Syntax
- Footer:** <http://www.viewclaim.com/a787/Approval/RuleWizard.asp> Trusted sites

- ❑ **Does your system compare OE pricing information?**
 - ❑ **YES. Enterprise *Workflow* compares all part type information (OE, aftermarket, recycled)**
- ❑ **If so, how?**
 - ❑ **Artificial Intelligence performs line-level price comparison analysis, regardless of estimating application**
 - ❑ **Recommendations can be made (OEM, recycled, etc.) based on policies and procedures established between trading partners**

- ❑ **What is your product roadmap?**
 - ❑ We continue to enhance and incorporate all necessary levels of functionality to meet the requirements for the Canadian marketplace
- ❑ **What components of your system are available in Canada now?**
 - ❑ All of the components of the system described in this presentation are available in Canada today
- ❑ **Coming in the future?**
 - ❑ Electronic database displaying Canadian recyclers
 - ❑ Expand assemblies search

Thank You